

SB, Tractor, SRD 77cm, Bagger Presence Extrusion Kit, 532 42 89-10

Subject: TRACTOR BAGGER PRESENCE

Complaint: Bagger presence hasn't been activated all times.
Extrusion was not correctly fixed.
Tractor stops upon engaging cutting deck.

Service Solution :

532 42 89-10, Bagger Presence Extrusion Kit.
Assembly instructions for end-user included

Models Effected: Tractors (ML -00)

96041013700, 96041013800, 96041009900, 96041012300,
96041012400, 96041009400, 96041009500, 96041014000

Production Solution: (ML -01)

Moving presence switch to left side and adding paddle (532 17 46-62)
to activate switch.
Remove sensitivity and make a more robust design, (Picture).

