

SB: Pop Up Sprinklers S80, S-CS, S-ES, S30
and S50

Article: 1569, 1552, 1553, 1554 and 1555



Reason: To prevent a misalignment of the nozzle by a robotic lawn mower a retrofit protection cap is now available. It will be snapped on the sprinkler nut.



New spare part: 1569-00.900.01 protection cap