

## **SB, Software Bundle 5825856-10C will be released soon, McCulloch P1, 2021-12**

### **Affected models**

<b>Model</b>	<b>Serial Range</b>
ROB R600	2016 and newer
ROB R800	2016 and newer
ROB R1000	2016 and newer

### **Affected markets**

All.

### **Description**

A new version of mower software will be released for the affected models (see above). The software will be released together with new release version 1.2 of customer upgrade tool (planned in 12/2021).

This includes the following changes:

- Charging current supervision.
- Bug fixes.

It is strongly recommended to update the mowers at next service!

### **Warranty reporting information**

Nothing in this SB can be subject to warranty claims. Warranty claims will not be accepted.

### **Revision History**

<b>Rev.</b>	<b>Date</b>	<b>Order id.</b>	<b>Description</b>
A	2021-12	00016037	Created